

## ■ Installation method

### 1. Installation environment

Windows XP      Windows Vista  
Windows 7 (32 bits)      Windows 7 (64 bits)  
Windows 8 (64 bits)      Windows 8.1 (64 bits)  
Windows 10 (64 bits)

※ Windows 8 (32 bits)      Windows 10 (32 bits)      It isn't tested  
Probably it will work.

### 2. Installation method

There is a [???\_setup.exe] file in a program folder.  
Double-click [???\_setup.exe]

"User Account Control"

The dialog will ask "Do you want to allow the following program to make changes to this computer?" Choose Yes.

The installation completes when pressing "next" to a message.

[Windows 7 (64 bits), Windows 8 (64 bits)]

If program execution was refused, Right-click a start-up icon, and select **Properties** from the menu.

Select [Compatibility] and [Privilege Level] and check box as [Run this program as an administrator] and save it.

It is possible to execute a start-up icon when doing the double-click.

[Windows 10 (64 bits), Windows 8.1 (64 bits)]

If program execution was refused, Right-click a start-up icon, and select **Properties** from the menu.

Select [Compatibility] and check box as [Run this program as an administrator] and save it.

It is possible to execute a start-up icon when doing the double-click.

## ■ Uninstallation

start → Control Panel → Addition and deletion of a program

It clicks the program to delete.

It presses the deletion button.

It closes the addition and deletion of a program.

The program to delete is following name.

Herical Cutting	Circle
Diagonal line Cut	Kozai
Chamfer Cutting	Mentori
Radial Chamfer	RMentori
Corner Plane	Kadomentori
1/1000 to 1/100	Ketasu100
Easy Profile	EasyPro
Stroke Check	StrokeCheck
NC Mirror	NcMirror
Axis Rotation	AxisRot
Dig Slots (offset)	Horikomi
Dig Slots (tool center)	HorikomiC
Base Plane Cutting	Teimen
Slide Cutting	Slide
Roughing Profile	AradoriPro
PROCAM-2D	PROCAM